

TOWN OF WEST SENECA



JOHN A. GULLO
CODE ENFORCEMENT OFFICER,
CFEI, CHS-IV, CDP-I

TOWN SUPERVISOR
SHEILA M. MEEGAN
TOWN COUNCIL
EUGENE P. HART
WILLIAM P. HANLEY, JR.

August 16, 2016

Honorable Town Board
Town of West Seneca

Re: 164 Edson Street
West Seneca, New York

Dear Honorable Town Board;

Please conduct a hearing for the removal of the unsafe conditions at the above captioned property for August 22, 2016.

The conditions set forth in Chapter 57 of the Town Code have been met without any responsible person replying.

A copy of the inspection report and the notice sent and posted is attached. Please note that in considering our action that the expenses will be placed on the assessment rolls.

If you have any questions please contact our office.

Respectfully Submitted;

A handwritten signature in black ink, appearing to read "John A. Gullo".

John A. Gullo
Senior Code Enforcement Officer

TOWN OF WEST SENECA



JOHN A. GULLO
CODE ENFORCEMENT OFFICER,
CFEI, CHS-IV, CDP-1

TOWN SUPERVISOR
SHEILA M. MEEGAN
TOWN COUNCIL
EUGENE P. HART
WILLIAM P. HANLEY, JR.

Date: June 21, 2016

Re: 164 Edson St
West Seneca, New York


Time: 9:00 am

Conditions: Clear, no Wind, approximately 74 degrees Fahrenheit.

Present: Joseph Rausch, Town Engineer
John Gullo, Senior Code Enforcement Officer

Observations:

- 1) The house has been vacated almost approximately 5 years to our knowledge
- 2) wood frame two family residence block foundation walls
- 3) The foundation walls are leaning inward on the north, south and west elevations.
- 4) The roof shows deterioration
- 5) The chimney appears to have loose bricks and broken mortar joints
- 6) Utilities are still connected
- 7) Obvious signs that vandals have entered and damaged interior
- 8) No porch railings
- 9) Obvious signs of vermin present
- 10) This is an attractive nuisance to the neighborhood


Joseph Rausch, Town Engineer

6/29/16


John Gullo, Code Enforcement Officer

